

Release Notes for Emulex BE Server Software v4.6.142.10

ESX NIC Driver

- * SRIOV: Need ESX driver support to provide VF's information to MILI
- * Random loss of network connectivity with 4 port NICs using teaming
- * PSOD with Firmware update on an Lancer CNA adapter
- * Some packets are transmitted out of order
- * Link does not come up after a down and up of port using esxcli
- * BE2 NICs using teaming traffic interrupted for 20 seconds during failback
- * VMKernel Log shows error message "Unhandled NETQUEUE OP 17"
- * Add new PCI subsystem device id and vendor id specific to OEM's
- * Losing network connectivity after several alloc_skb() failure messages in log.